

FITNESS CERTIFICATE
[To be filled in by the Inspecting Officer]

No.08/AEE/KBP/2022-23.

Dated. 13.10.2022.

1	Name of Officer	THOMAS D'CRUZ K J.
2	Name of School	Sree Sankara English Medium School, Kuruppankulangara P O, Cherthala,Alappuzha- 688539.
3	Location with name of Education Dist./ Sub. Dist	Cherthala
4	Classification of building as specified in column 4 of the application for fitness certificate and size	THIRD FLOOR. Class Room. 1. 3x800x600x360 cm Hall 2. 1x1735x600x360 cm
5	Period for which the certificate is issued	2022-2023.
6	Name of defect if any	
a	Foundation and Basement	Nil
b	Superstructure	Nil
c	Doors and windows	Nil
d	Wood work wrought and put up	Nil
e	Roof	Nil
f	Flooring	Nil
g	Miscellaneous (cracks etc.)	Nil
7	Any major defects noticed which will render the building unsafe in any manner	Nil
8	Whether maintenance works have done properly	New Building
9	Whether the structure is sound or not	Sound under the normal weather condition of Kerala

Note:- 1. The stability of the structure should be examined also with reference to location, altitude, Intensity of wind, exposure to flood etc.

2. Any additional observations if deemed necessary for the certificate may be furnished separately with the certificate

Certified that the school was inspected by me on **13.10.2022.** and found to be fit/ unfit to conduct classes for the period from **2022-2023** for the reason stated above.

Place: S.N. Puram
Date: 13.10.2022



ASST. EXECUTIVE ENGINEER,
LSGD SUB DIVISION, KANJIKKUZHY BLOCK PT.
Assistant Executive Engineer
LID & EW Division
Kanjikkuzhy Block Panchayath

FITNESS CERTIFICATE

(To be filled by the inspecting officer)

Name of school Sree Sankara English Medium school ,Kuruppankulangara
Name of Officer Deepthi.G
Location with name of Education Dist/Sub Dist Alappuzha/Cherthala
Classification of building as specified in column 4 of application for fitness certificate and size Multi storeyed building with verandah having RCC roof - south building (Jubilee Building)
G F -6.00x6.00x3.60-1 No
G F 8.00x6.00x3.60-4 Nos
F F -14.20x6.00x3.60 -1 No
F F -8.00x6.00x3.60- 3 Nos
S F -6.00x6.00x3.60 - 1No
S F -8.00x6.00x3.60 - 4 Nos
Multi storeyed building with verandah having RCC roof - East building
G F 6.20x6.00x3.56-6 Nos
F F -6.20x6.00x3.56 Nos
S F -6.20x6.00x3.70 - 1No
S F -6.20x6.00x2.80 - 4 Nos with Sheet roofing having E board ceiling
Multi storeyed building with verandah having RCC roof - North building
G F 6.00x6.45x3.00-6 Nos
F F -6.00x6.45x3.00-6 No
S F -9.25x6.45x3.00 - 2No
S F -6.1x6.45x3.00- 3 Nos
T F -5.95x6.45x3.00 - 4 nos Sheet roofing with ceiling
T F - 6.15 x 6.45 x 3.00 - 2 nos Sheet roofing with ceiling
Period for which certificate is issued 2022-23
Nature of defects if any Nil
Foundation & Basement
Supers'tructure
Doors and windows Nil
Wood work wrought and put up
Roof
Flooring
Any major defects found which will render the buiding unsafe in in any manner Nil
Whether maintenance work has been done properly Yes
Whether the structure is sound or not for conducting classes Sound under normal weather conditions of Kerala
The stabiility of the structure should be examined also with reference to location,alitude ,intensity of wind,exposure to flood etc

Any additional observations if deemed necessary for the certificate may be furnished separately with the certificate

Certified that the school was inspected by me on 28/09/2022 and found to be fit to conduct class for the period 2022-23 for the reasons stated above

Place Areeparampu
date 29.09.2022.



ASSISTANT ENGINEER
L.S.G.D SECTION
CHERTHALA SOUTH
GRAMA PANCHAYATH